

# "His people today are to remember that the house of worship is the Lord's property and that it is to be scrupulously cared for."

(Testimonies for the Church, vol. 9, p. 248)

#### **OUR BEGINNINGS**




**Central Tract Society, 1926** 

Church on 23<sup>rd</sup> Street, 1940-50




# **CHURCH PLANTS by 1962**



# ARISE & BUILD, 1965-70







# God has done great things for us!



#### **CURRENT CAMPUS NEEDS...**



## Aged, inefficient & dilapidated HVAC system ...



#### Old & run-down classroom roof...











# **Decrepit courtyard**











# Decrepit parking lot & driveway



#### Deteriorated slatted wall, trellis & fences





#### **Run-down Sabbath School classrooms**



# **CURRENT MISSION NEEDS No Churches In...**




Folsom, CA (Pop. 74,000)


Natomas, CA (Pop. 190,000)

# **Proposals for Campus Needs...**




## **Existing Sanctuary HVAC System**






#### Recommended Replacement (cont.)



#### Sanctuary HVAC System



**Condition:** Needs replacement with more efficient system. Strengthen roof.

**Recommendation:** Phase replacement over a 3-year period.

**Cost:** Phase 1-3 / \$233,700 Phase 4 / 168,000 Phase 5 / 88,000

## **Courtyard/Classroom Roof**



**Condition:** Needs resurfacing, not replacement

**Recommendation:** Resurface with Elastomeric

**Cost:** \$86,000

## **Courtyard**



**Condition:** Severe cracking, lifted surface in areas, planters splitting

**Recommendation:** Repave courtyard, repair planters and fountain.

**Cost:** \$70,000

## Parking Lot / Driveway



**Condition:** Swelling, contusions, major cracking.

**Recommendation:** Grind, dig out, and replace asphalt, fix tree wells, replace trees.

**Cost:** \$268,000

## Slatted Wall / Trellis / Fences



**Condition:** Rotted beams, age, and wear & tear.

Recommendation: Patch, repair & paint slats. Replace fence. Replace rotted beams with painted pressure treated lumber.

Cost: \$15,000

#### Sabbath School Classrooms



**Condition:** Age and wear & tear.

**Recommendation:** Replace carpet, windows, cupboards, and add air conditioning.

Cost: \$22,000

See next slide for renovation idea

#### Primary Room Renovation



# **Proposals for Mission Needs...**



## **Church Growth / Church Plant**





Condition: Membership in minimal decline (primarily due to transfers). Attendance needs to improve.

Recommendation: Raise church attendance & increase baptisms through Total Member Involvement (TMI). With projected increases fulfilled, plant new church.



## **5-Year Strategy**

See form by same name...



- \* Current Building Value \$10 million +
- \* Other major renovations already completed

- \* Repair/renovate as funds become available
  - \* A call for experience as well as funds
  - \* Maintain current budget of \$397,000/yr
- \* Amount needed is 8% of value of building

## **Funding Option\$ for Building Program**

\* Capital Campaign

\* Vendor Donations/Discounts

\* Member Labor Contributions

"Our heavenly Father has a thousand ways to provide for us of which we know nothing..."

Desire of Ages, p. 330